



Figure 50. Metal Spray Deposits on the Third-Stage Turbine Blades